

**Port Marine Notice****Port of: Jebel Dhanna Ruwais****No.JDR/MN/047/2025****Date: 03/12/2025**

**To : All Shipping  
Shipping Agents  
Port Users  
Port Operators**

**Type of Change: Temporary****Subject: Marker Buoy Drifted – Not in position**

Please be advised that Sea Water Outfall Pipe marker buoy is currently not in position . The buoy has been drifted from its' charted position and retrieved.

<b>Buoy Name</b>	<b>Latitude</b>	<b>Longitude</b>	<b>Light</b>	<b>Remarks</b>
Marker buoy	24° 08' 40.11" N	052° 44'.45.46" E	Fl (2) Y 5s	Not in position

**Caution: N/A**

Contact Ruwais VTIS on Ch.16 and 21 for further information.

Any clarification related to this Port Marine Notice, may be directed to the Harbor Master using Contact us form on PPA website <https://ppa.adnoc.ae/en/contact-us>

**Harbour Master****Port of : Jebel Dhanna Ruwais**

