

PORT AUTHORITY OF JD/RUWAIS

PORT MARINE CIRCULAR
NO. 002 of 2016

March 3, 2016

To Ruwais Station Manager/Ruwais Port Control/VTIS

USE OF PILOT COMBINATION LADDER

During review of a recent "Vessel Feedback" report, it was noted that, while a vessel has prepared the combination ladder as appropriate and as directed by the Port Control, the pilot requested to embark the vessel using the accommodation ladder only.

The reasons declared by the pilot -on a later date- were that the combination ladder was in a poor condition and was not appropriately rigged.

It is therefore incumbent on a pilot, should he choose not to use the vessel's Combination Ladder due to its poor condition or inappropriate arrangements, that the matter is reported immediately to the Port Control and a Deficiency Report be completed and forwarded to the Harbor Master.

CAPT. PAUL HANSON



HARBOUR MASTER
PORT AUTHORITY OF JD/RUWAIS