Business and Commercial Support Directorate Petroleum Ports Authority FORM NO. PPA-FRM-002



PETROLEUM PORTS AUTHORITY MARINE NOTICE No. 005/16

Station/Port.:	DAS/ZIRKU/MUBARRAZ	Date: 05/12/2016	Priority:	\boxtimes	Urgent
Ref No:	PPA/DAS/MN/005/16				Normal

SUBJECT: Mooring Buoy

DATE: With Effect from 05th Dec 2016

LOCATION/POSITION: East of Das Island Extension (Chart Attached)

DETAILS / INFORMATION

This Marine Notice brings to your attention that the Mooring Buoys (MB) deployed in the position below are unlit, therefore due diligence must be exercised whilst operating in this area.

Buoy Name	Colour	Latitude	Longitude
MB 1	Yellow	25° 07.13'	52° 54.42'
MB 2	Yellow	25° 06.81'	52° 53.87'

CAUTION: When in vicinity of the area, marines are reminded to:

- a) Maintain a proper lookout.
- b) Proceed at a safe speed and navigate with caution.
- c) Maintain a listening watch on VHF Channel 12/23 (Das Port Control/VTIS).All movements shall be coordinated with VTIS
- d) Anchoring prohibited adjacent to the pipeline.

For Petroleum Ports Authority

Name: Capt. Siby John

Title: Port Officer

Signature:



