

Port of: **Das Zirku & Mubarraz**

Port Marine Notice

No. DZM/MN/018/2018

17/04/2018

To: **All Shipping**
Port Users
Shipping Agents
Port Operators

Subject: Navigational Buoy Unlit

Note: This Marine Notice supersedes Marine Notice DZM/MN/017/2018.

Please be advised that, the below mentioned navigational buoy is unlit.

Buoy Name	Light Characteristics	Latitude	Longitude	Type
DW TSS Buoy No.4	Fl. R. 2s	25°22.24' N	053°11.12' E	Port Hand Lateral Mark

Note: SPM # 3 Fl. R. 5s, 25°08.94' N 052°54.13' E Single Point Mooring Lt is now operational.

Caution: Mariners are to exercise caution whilst transiting this area and keep a continuous listening watch on VHF channels 12/23 (Das Port Control/VTIS).

Any clarification related to this **Port Marine Notice**, may be directed to the Harbor Master at
Tel: +971 260 28999/ppadas@adnoc.ae/vtisdas@adnoc.ae

Harbour Master

Port of: **Das Zirku & Mubarraz**

