

Port Marine Notice

Port of: **Das Zirku & Mubarraz**

No. DZM/MN/014/2026

Date: 09.08.2026

To: **All Shipping
Shipping Agents
Port Users
Port Operators**

Type of Change: **Temporary**

Subject: Mooring Buoy (TMB 1) with Light

Please be advised that TMB No. 1 has been now fitted with 2 flashing lights . The light characteristics are as follows.

Buoy No	Type	Latitude	Longitude	Flash Characteristic
TMB 1	Mooring Buoy	25 ⁰ 08."497" N	052 ⁰ 53"374" E	Fl Y 4s

All vessels and crafts are requested to navigate with caution while transiting the area.

Caution: When in the vicinity of the location mariners are reminded to:

- a) Maintain a proper lookout, proceed at safe speed, and navigate with caution.
- b) Keep well clear of the Mooring buoy area.
- c) Maintain a listening watch on VHF Channel 23 (Das VTIS)

Any clarification related to this Port Marine Notice, may be directed to the Harbor Master using Contact us form on PPA website <https://ppa.adnoc.ae/en/contact-us>

 

Harbor Master

Port of: **Das Zirku & Mubarraz**

